

### Compliance Certificate Audits

	Oct-22 No.	FY22-23 YTD No.
Compliance Certificates Audited	586	2,642
Audits Failed	86	382
Percentage of Failed Audits	15%	14%
Re-Audits Conducted	66	224
No Access	48	164

#### Top 3 Causes of Audit Failure:

1. To provide the appropriate clearance from the balanced flue terminal. (14)
2. To provide appropriate overflow provision to the roof drainage system. (14)
3. To provide the minimum clearance between the highest part of the burner and the range-hood or exhaust fan. (8)


### Drain Inspections

	Oct-22 No.	FY22-23 YTD No.
Drains Inspected	215	586
Drains Failed	28	68
Percentage of Failed Inspections	13%	12%
Re-inspections Conducted	32	79
Not Ready Drains	97	249
Test Prior	-	3

#### Top 3 Causes of Inspection Failure

1. To support the fitting with concrete, in the appropriate position. (12)
2. To reconstruct the defective property sewerage drain, to withstand the air test requirements. (10)
3. To provide continuous support to the property sewerage drain. (9)

Compliance Certificates Lodged YTD: 181,859



Drains Offered YTD: 17,905

