

### Compliance Certificate Audits

	Nov-22 No.	FY22-23 YTD No.
Compliance Certificates Audited	330	2,972
Audits Failed	33	415
Percentage of Failed Audits	10%	14%
Re-Audits Conducted	61	285
No Access	43	207

#### Top 3 Causes of Audit Failure:

1. To provide the minimum clearance between the highest part of the burner and the rangehood or exhaust fan. (5)
2. To provide the required size/number of downpipes for the roof catchment. (4)
3. To provide appropriate overflow provision to the roof drainage system. (3)


### Drain Inspections

	Nov-22 No.	FY22-23 YTD No.
Drains Inspected	218	804
Drains Failed	14	82
Percentage of Failed Inspections	6%	10%
Re-inspections Conducted	21	100
Not Ready Drains	79	328
Test Prior	-	3

#### Top 3 Causes of Inspection Failure

1. To support the fitting with concrete, in the appropriate position. (8)
2. To reconstruct the defective property sewerage drain, to withstand the air test requirements. (6)
3. To provide continuous support to the property sewerage drain. (5)

### Compliance Certificates Lodged YTD: 229,143



### Drains Offered YTD: 22,815

