

### Compliance Certificate Audits

	Feb-23 No.	FY22-23 YTD No.
Compliance Certificates Audited	239	3,602
Audits Failed	28	485
Percentage of Failed Audits	12%	13%
Re-Audits Conducted	19	329
No Access	18	252

#### Top 3 Causes of Audit Failure:

1. To reconstruct, the downpipe spreaders in an approved manner. (11)
2. To strengthen the appropriate supports, to withstand wind forces. (8)
3. To provide appropriate overflow provision to the roof drainage system. (7)


### Drain Inspections

	Feb-23 No.	FY22-23 YTD No.
Drains Inspected	279	1,368
Drains Failed	37	142
Percentage of Failed Inspections	13%	10%
Re-inspections Conducted	39	176
Not Ready Drains	77	464
Test Prior	-	3

#### Top 3 Causes of Inspection Failure

1. To reconstruct the defective property sewerage drain, to withstand the air test requirements. (19)
2. To provide continuous support to the property sewerage drain. (12)
3. To support the fitting with concrete, in the appropriate position. (11)

### Compliance Certificates Lodged YTD: 345,971



### Drains Offered YTD: 33,967

